Montana Board of Oil and Gas Conservation **Environmental Assessment**

Operator: TAQA North USA, Inc.
Well Name/Number: Hellegaard 8-8H
Location: SE NE Section 8 T37N R57E
County: Sheridan , MT; Field (or Wildcat) Wildcat (Flat Lake)
Air Quality
(possible concerns)
Long drilling time: No. 20-30 days drilling time.
Unusually deep drilling (high horsepower rig): Heavy double derrick drilling rig 900-1000 HP
(Estimated) to drill a Bakken formation single lateral horizontal well, 11,930'MD/7,798'TVD.
Possible H2S gas production: Slight
In/near Class I air quality area: No Class I air quality area nearby.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-
<u>211.</u>
Mitigation:
X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: Existing field infrastructure to handle gas. No concerns.
W-4 O - P4-
Water Quality
(possible concerns)
Salt/oil based mud: Intermediate string hole will be drilled with oil based invert mud system and openhole
horizontal production hole will be drilled with fresh water polmer drilling fluids. Surface casing hole will
be drilled with a freshwater, and freshwater mud system.
High water table: No high water table anticipated.
Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral drainage, about 3/8 of

drilling muds. The surface casing setting depth. of 1250' should be below all freshwater zones. Porous/permeable soils: No, sandy clay soils.

Class I stream drainage: No, Class I stream drainages.

Mitigation:

- Lined reserve pit
- X Adequate surface casing
- ___ Berms/dykes, re-routed drainage _X Closed mud system
- \underline{X} Off-site disposal of solids/liquids (in approved facility)
- X Other: Freshwater drilling fluids will be land applied with surface owner approval.

Comments: 1250' surface casing well below freshwater zones in adjacent water wells. Also, covering Fox Hills aquifer. Adequate surface casing and BOP equipment to prevent problems in and around freshwater slough.

a mile to the north from this location. Pothole lake about ½ of a mile to the west from this location. Water well contamination: None, closest water wells in the area are about 3/8 of a mile to the southwest, 5/8 of a mile to the northwest and 5/8 of a mile to the east from this location. Depth of these domestic and stockwater wells are 200' and shallower. Surface hole will be drilled with freshwater and freshwater

Soils/Vegetation/Land Use

Steam crossings: None anticipated.
High erosion potential: Small cut, up to 5.7' and small fill, up to 9.9', required.
Loss of soil productivity: None, location to be restored after drilling well, if nonproductive. If productive
unused portion of drillsite will be reclaimed.
Unusually large wellsite: No, large well site 400'X490'
Damage to improvements: Slight, surface use is a cultivated field.
Conflict with existing land use/values: <u>Slight</u>
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments: Access will use existing county road, Ueland Road, a section line road and existing lease
road. A short road of about 11' will be built off the lease road into this location Surface hole
(freshwater) cuttings will be mixed buried on site Oil based invert mud cuttings will be trucked to an
approved waste disposal facility. Oil based drilling fluids will be recycled to the next location or returned
to the mud company's recycling facility. Freshwater surface fluids and horizontal freshwater polymer
fluids and cuttings will be land applied. No concerns.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: Residence ½ of a mile to the northwest and 1 mile to the
southeast from this location.
Possibility of H2S: _Yes, slight.
Size of rig/length of drilling time: <u>Heavy double drilling rig 20 to 30 days drilling time.</u>
Mitigation:
_X Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments: Adequate surface casing cemented to surface with working BOP stack should
mitigate any problems.
***** N**O /
Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No
Threatened or endangered Species: Only species identified as threatened or endangered are the Whooping
Crane and Piping Plover. Candidate species is the Spragues Pipit. NH Tracker site indicates 14 species of
concern. All are migratory birds.
Mitigation: Avoidance (topographic tolerance/exception)
A VOIGANCE (TOPOGLAPING TOTETANGE/EXCEPTION)
Other agency review (DFWP, federal agencies, DSL)

(possible concerns)

Comments: Private cultivated surface lands. No concerns.
Historical/Cultural/Paleontological (possible concerns) Proximity to known sites:None identified. Mitigationavoidance (topographic tolerance, location exception)other agency review (SHPO, DSL, federal agencies)Other: Comments:Private cultivated surface lands. No concerns.
Social/Economic (possible concerns) Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns. Wildcat well within an existing oil field, Flat Lake Field.
Remarks or Special Concerns for this site
Wildcat Bakken formation horizontal well within an existing oil field, Flat Lake Field
Summary: Evaluation of Impacts and Cumulative effects No long term impacts expected. Some short term impacts will occur, but can be mitigated in a short time.
I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u>) require the preparation of an environmental impact statement. Prepared by (BOGC): /s/Steven Sasaki
(title:) Chief Field Inspector Date: December 2, 2010 Other Persons Contacted: Montana Bureau of Mines and Geology, Groundwater Information Center website.
(Name and Agency) Sheridan County water wells (subject discussed)

_ <u>December 2, 2010</u>
(date)
US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA
COUNTIES, Sheridan County
(subject discussed)
(date)
Montana Natural Heritage Program Website (FWP) (Name and Agency) Heritage State Rank= S1, S2, S3, T37N R57E (subject discussed)
_December 2, 2010
(date)
If location was inspected before permit approval: Inspection date: _12/3/2010 Inspector:Schmidt Others present during inspection:None